

DEPARTMENT of ENVIRONMENTAL SERVICES
Water Supply & Pollution Control Division - Biology Bureau

LAKE TROPHIC DATA

MORPHOMETRIC:

Lake: DODGE POND	Lake Area (ha): 5.06
Town: NEW BOSTON	Maximum depth (m): 3.0
County: Hillsborough	Mean depth (m): 1.0
River Basin: Merrimack	Volume (m ³): 49000
Latitude: 42°59'47" N	Relative depth: 1.2
Longitude: 71°41'42" W	Shore configuration: 3.07
Elevation (ft): 495	Areal water load (m/yr): 31.16
Shore length (m): 2450	Flushing rate (yr ⁻¹): 32.20
Watershed area (ha): 327.0	P retention coeff.: 0.43
% watershed ponded: 0.1	Lake type: natural

BIOLOGICAL:

5 February 1998

29 July 1997

DOM. PHYTOPLANKTON (% TOTAL)	#1	SPARSE - NO DOMINANT	CHRYSOSPHAERELLA 60%
	#2		
	#3		
PHYTOPLANKTON ABUNDANCE (units/mL)			
CHLOROPHYLL-A (µg/L)			17.21
DOM. ZOOPLANKTON (% TOTAL)	#1	LRG RND CILIATE SPP 44%	KERATELLA 25%
	#2	KELLICOTTIA 31%	CALANOID COPEPOD 13%
	#3	KERATELLA 22%	CYCLOPOID COPEPOD 12%
ROTIFERS/LITER		265	132
MICROCRUSTACEA/LITER		12	122
ZOOPLANKTON ABUNDANCE (#/L)		495	254
VASCULAR PLANT ABUNDANCE			Very abundant
SECCHI DISK TRANSPARENCY (m)			1.8
BOTTOM DISSOLVED OXYGEN (mg/L)			0.3
BACTERIA (E. coli, #/100 ml)	#1		
	#2		
	#3		

SUMMER THERMAL STRATIFICATION:

weakly stratified

Depth of thermocline (m): None
Hypolimnion volume (m³) : None
Anoxic volume (m³) : 1500

CHEMICAL:

Lake: DODGE POND

Town: NEW BOSTON

	5 February 1998		29 July 1997		
DEPTH (m)	1.0	3.0	1.0		2.0
pH (units)	5.7	5.7	6.6		6.4
A.N.C. (Alkalinity)	6.5	13.0	8.7		9.1
NITRATE NITROGEN	0.18	0.05	< 0.05		< 0.05
TOTAL KJELDAHL NITROGEN	0.40	0.80	0.60		0.70
TOTAL PHOSPHORUS	0.036	0.045	0.029		0.038
CONDUCTIVITY (μ mos/cm)	129.9	147.2	94.6		93.2
APPARENT COLOR (cpu)	40	55	36		38
MAGNESIUM			1.14		
CALCIUM			4.4		
SODIUM			12.1		
POTASSIUM			0.29		
CHLORIDE	30	31	20		20
SULFATE	6	7	3		3
TN : TP	16	19	21		18
CALCITE SATURATION INDEX			3.1		

All results in mg/L unless indicated otherwise

TROPHIC CLASSIFICATION: 1997

D.O. S.D. PLANT CHL TOTAL CLASS


**	4	6	3	13	Eutro.
----	---	---	---	----	--------

COMMENTS:

1. This is essentially a very small pond (see bathymetric map) that was raised by a beaver dam. When the dam is out, only the 10 foot contour remains as a pond, surrounded by a wet meadow.
2. Two beaver huts were present.
3. This is a very productive pond with abundant macrophyte growth, elevated chlorophyll levels and poor clarity. Sodium and chloride levels suggest some salted road runoff.


Dodge Pond New Boston

5 foot depth contours



[illegible]

Dodge Pond New Boston



[illegible]